RAVAS ASCII PROTOCOL INDICATOR 3200 and 5200





Contents

RAVAS ASCII PROTOCOL
Transfer Protocol for wired connection over the RS232 port
Transfer Protocol for wireless connection over the BLE port
Setup for Servicing 3200 indicator3
Setup for Servicing 5200 indicator4
ASCII commands5
SERVICE commands
Special commands 'GW' and 'SW'7
Special commands 'AN' and 'AG'8
Errors returned to PC9
Special command 'P85' (only for 3200 indicator used for servicing)10
Special command 'GE'11
Explanation data lines12
Error list indicator 320012
Error list indicator 520013
Special command 'RE'14
Special command 'GI'16
Example of information logging indicator 3200:16
Explanation data lines17
Example of information logging indicator 5200:18
Special command 'GS'
Example of status logging indicator 3200:20
Explanation data lines
Example of status logging indicator 5200:23
Special command 'GL'
Special command [SL] (Version 0.32 and higher)24

RAVAS ASCII PROTOCOL

The indicators 3200/5200 offer the possibility to communicate bi-directional with a PC or other hardware devices which can handle simple ASCII commands. (For activation of this application setting, please contact your scale dealer.)

Transfer Protocol for wired connection over the RS232 port:

Baudrate- 9600 Databits- 8 Stopbits- 1 Parity- none Handshake-none

Transfer Protocol for wireless connection over the BLE port:

Baudrate- 115200 Databits- 8 Stopbits- 1 Parity- none Handshake-none

Setup for Servicing 3200 indicator

For using the Servicing Commands, the proper data protocol of the selected communication port of the indicator should be set. Please follow next instructions;

- Press the totalizing button (no. 3) for 12 seconds until the display shows [USEr]
- Press the totalizing button shortly. The display will show [SUP.]
- Press the enter button (no. 1 from the left) shortly to enter the Supervisor Menu. The display will show [00000] with the most right digit blinking. For entering the supervisor mode a password is required.
- Enter the password [05220] and press the enter button. The display will show [bLE] which stands for the Bluetooth port.
 If the communication needs to be handled over the wired RS232 port you need to push the totalizing button shortly. Next proceed with the following steps;
- Press the enter button shortly to enter the Bluetooth (or RS232) port settings.

The displays default is [NonE] but it is possible that another data protocol has been set. In that case note down this and underlying settings so you will be able to restore the same settings after servicing. For going through these settings please check the Supervisor flow diagram at the back of this manual.

If the default value [NonE] is set proceed with following steps;

- Press the totalizing button shortly. The display will show [PC]
- Press the enter button shortly to enter the PC settings. The display will show [bidir]
- Press the enter button shortly to enter the PC settings. The display will shortly show [SEt] and next return to the main Supervisor menu [SUP.]
- Press the On/Off button (no.5 from the left) shortly to return to the weighing mode.

Setup for Servicing 5200 indicator

For using the Servicing Commands, the proper data protocol of the selected communication port of the indicator should be set. Please follow next instructions;

- Press the arrow down key twice.
- Press the settings key.
- Select "Service Menu.
- Enter the password [5220] and press the enter button.
- Select "Communication".
- Select "BLT4.0 on-board".
- Select "Info".
 On the next page you will see the Bluetooth address of the module and whether it is connected or not to a device.

If you want to use the RS232 port for servicing, please follow next instructions;

- Press the arrow down key twice.
- Press the settings key.
- Select "Service Menu.
- Enter the password [5220] and press the enter button.
- Select "Communication".
- Select "RS232 on-board".
- Select "Protocol".
- Select "PC".
- Press "Enter".
- Select for Stopbits [1], for Databits [8], for Parity [None] and for Baudrate [9600].

Press "Back" several times to return to the main screen.

ASCII commands*2

RZ <cr> OK<cr>/ERR<cr> Reset zero value SP<value><cr>*1 OK<cr>/ERR<cr> Set preset tare value RR<cr> OK<cr>/ERR<cr> Reset preset tare RT<cr> OK<cr>/ERR<cr> Reset tare ST<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare (also with a previous tare) *3 SG<cr> G+0001.0 Send gross mode (continuously) SN<cr> N+00010+000103805 Send angle positions X and Y (continuously) SA See chapter SL command Similar to SW but including errors GP<cr> P+0001.0 Get preset tare Get continuously) SL<cr> See chapter SL command Similar to SW but including errors GP F+0001.0 Get preset tare Get cres GT<cr> P+0001.0 Get gross Get net GN See chapter GL command Set angle positions X and Y GCCR> M+000.0 Get gross, status and checksum GA A;+000.0 Get gross, status and checksum</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></value></cr></cr></cr>	ASCII command	Response string	Operation		
SP <value><cr>*1 OK<cr>/ERR<cr> Set preset tare value RP<cr> OK<cr>/ERR<cr> Reset preset tare RT<cr> OK<cr>/ERR<cr> Reset tare ST<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare (also with a previous tare)*3 SG<cr> G+0001.0 Send gross mode (continuously) SN<cr> N+0001.0 Send net mode (continuously) SW W+00010+000103805 Send angle positions X and Y (continuously) SN<cr> W+000.0;+000.0 Send angle positions X and Y (continuously) SL<cr> See chapter SL command Similar to SW but including errors GP<cr> P+0001.0 Get preset tare Get care GG<cr> G+0001.0 Get tare Get care GG<cr> H+0001.0 Get tare Get care GG G+0001.0 Get tare Get care GG G+0001.0 Get angle positions X and Y Get care GG G+0001.0 Get angle positions X and Y Get care GG Get ont Get net <td< td=""><td>SZ<cr></cr></td><td>OK<cr>/ERR<cr></cr></cr></td><td>Set zero value</td></td<></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></value>	SZ <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set zero value		
RP <cr> OK<cr>/ERR<cr> Reset preset tare RT<cr> OK<cr>/ERR<cr> Reset tare ST<cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare (also with a previous tare) "3 SG<cr> G+0001.0 Send gross mode (continuously) SN<cr> N+0001.0 Send net mode (continuously) SW W+00010+000103805 Send net mode (continuously) SA<cr> M+0001.0 Send angle positions X and Y (continuously) SL See chapter SL command Similar to SW but including errors GP<cr> P+0001.0 Get preset tare Get care GG<cr> G+0001.0 Get tare Get care GG<cr> G+0001.0 Get net Get net GW W+00010+000103805 Get net Get net GW M+0001.0 Get care Get care Get care GG G+0001.0 Get care Get net Get care GG Get opter GE command Read out of last 50 messages Get care GS See chapter GE command Read out of general info and parameters <td< td=""><td>RZ<cr></cr></td><td>OK<cr>/ERR<cr></cr></cr></td><td>Reset zero value</td></td<></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	RZ <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset zero value		
RT <cr>OK<cr>/ERR<cr>Reset tareST<cr>OK<cr>/ERR<cr>Set tareSG<cr>G+0001.0Send gross mode (continuously)SN<cr>N+0001.0Send ner mode (continuously)SN<cr>N+0001.0Send ner mode (continuously)SW<cr>W+00010+000103805Send ner mode (continuously)SSSSSend ner mode (continuously)SSSecRaW+00010+000103805SWA;+000.0;+000.0Send angle positions X and Y (continuously)SL<cr>See chapter SL commandSimilar to SW but including errorsGP<cr>P+0001.0Get preset tareGT<cr>T+0001.0Get grossGN<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGG<cr>G+0001.0Get areGS<cr>See chapter GLGet netGW<cr>W+00010.0Read out of last 50 messagesGI<cr>See chapter GL commandRead out of status and checksumGL<cr>See chapter GL commandRead out of status and calibrationGL<cr>See chapter GL commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandRead out of status and calibrationGL<cr>See chapter RE commandReat ou</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SP <value><cr>^{*1}</cr></value>	OK <cr>/ERR<cr></cr></cr>	Set preset tare value		
ST <cr> OK<cr>/ERR<cr> Set tare SR<cr> OK<cr>/ERR<cr> Set tare (also with a previous tare) *3 SG<cr> G+0001.0 Send gross mode (continuously) SN<cr> N+0001.0 Send net mode (continuously) SW W+00010+000103805 Send net mode (continuously) SW W+00010+000103805 Send angle positions X and Y (continuously) SA<cr> A;+000.0;+000.0 Send angle positions X and Y (continuously) SL<cr> See chapter SL command Similar to SW but including errors GP<cr> P+0001.0 Get preset tare GT<cr> T+0001.0 Get tare GG<cr> G+0001.0 Get gross GN<cr> N+0001.0 Get gross GN<cr> W+00010+000103805 Get net GW GW Get ores, gross, status and checksum GA GA Get ores, gross, status and checksum GA A;+000.0;+000.0 Get angle positions X and Y GE See chapter GE command Read out of last 50 messages GI<cr> See chapter GL command Read out of status and calibration GL GL</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	RP <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset preset tare		
SR <cr> OK<cr>/ERR<cr> Set tare (also with a previous tare) *3 SG<cr> G+0001.0<cr> Send gross mode (continuously) SN<cr> N+0001.0<cr> Send net mode (continuously) SW W+00010+000103805<cr>*2 Send angle positions X and Y (continuously) SA<cr> A;+000.0;+000.0<cr> Send angle positions X and Y (continuously) SL<cr> See chapter SL command Similar to SW but including errors GP<cr> P+0001.0<cr> Get preset tare GG<cr> G+0001.0<cr> Get gross GN<cr> N+0001.0<cr> Get net GW<cr> N+0001.0<cr> Get net GW<cr> N+0001.0<cr> Get net GW<cr> W+00010+000103805<cr> Get net GA GH Get net GW<cr> N+0001.0<cr> Get net GA See chapter GE command Read out of last 50 messages GI<cr> See chapter GE command Read out of status and calibration GL<cr> See chapter GL command Read out of status and calibration GL<cr> See chapter GL command Read out of status and calibration GL<cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	RT <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Reset tare		
SG <cr> G+0001.0<cr> Send gross mode (continuously) SN<cr> N+0001.0<cr> Send net mode (continuously) SW<cr> W+00010+000103805<cr>*2 Send weights mode (continuously) SA<cr> A;+000.0;+000.0<cr> Send angle positions X and Y (continuously) SL<cr> See chapter SL command Similar to SW but including errors GP<cr> P+0001.0<cr> Get preset tare GT<cr> T+0001.0<cr> Get gross GN<cr> G+0001.0<cr> Get net GW GV Get out including errors GA Get Option CR> Get tare GG Get Option CR> Get tare GG Get Option CR> Get net GW W+00010+00103805 Get net GW W+00010+00103805 Get net GW See chapter GE command Read out of last 50 messages GI See chapter GE command Read out of general info and parameters GS See chapter GI command Read out of status and calibration GL GL See chapter GL command Read out total log file RE See chapter GL command</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	ST <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set tare		
SN <cr> N+0001.0<cr> Send net mode (continuously) SW<cr> W+00010+000103805<cr>*2 Send weights mode (continuously) SA<cr> A;+000.0;+000.0<cr> Send angle positions X and Y (continuously) SL<cr> See chapter SL command Similar to SW but including errors GP<cr> P+0001.0<cr> Get preset tare GT<cr> T+0001.0<cr> Get arre GG<cr> G+0001.0<cr> Get net GW<cr> W+00010+000103805 Get net GW<cr> W+00010+000103805 Get net GW<cr> N+0001.0 Get angle positions X and Y GE GEt command Read out of last 50 messages GI<cr> See chapter GL command Read out of status and calibration GL<cr> See chapter GL command Read out total log file RE<cr> See chapter GL command Read out total log file RE<cr> See chapter RE command Read out total log file RE<cr> See chapter RE command Reset the ERRORs database (passcode required) MN<cr> N+0001.0<cr>/ERR<cr>*4 Get net, wait for no motion MG<cr> G+0001.0;0001<cr>/ERR<cr>*4 Get n</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SR <cr></cr>	OK <cr>/ERR<cr></cr></cr>	Set tare (also with a previous tare) *3		
SW <cr>W+00010+000103805<cr>*2Send weights mode (continuously)SA<cr>A;+000.0;+000.0<cr>Send angle positions X and Y (continuously)SL<cr>See chapter SL commandSimilar to SW but including errorsGP<cr>P+0001.0<cr>Get preset tareGT<cr>T+0001.0<cr>Get grossGN<cr>G+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GI commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionASS+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SG <cr></cr>	G+0001.0 <cr></cr>	Send gross mode (continuously)		
SA <cr>A;+000.0;+000.0<cr>Send angle positions X and Y (continuously)SL<cr>See chapter SL commandSimilar to SW but including errorsGP<cr>P+0001.0<cr>Get preset tareGG<cr>G+0001.0<cr>Get grossGN<cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GI commandRead out total log fileRE<cr>See chapter RE commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SN <cr></cr>	N+0001.0 <cr></cr>	Send net mode (continuously)		
SL <cr>See chapter SL commandSimilar to SW but including errorsGP<cr>P+0001.0<cr>Get preset tareGT<cr>T+0001.0<cr>Get tareGG<cr>G+0001.0<cr>Get grossGN<cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<<cr>/ERR<cr>*4Get net and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SW <cr></cr>	W+00010+000103805 <cr>*2</cr>	Send weights mode (continuously)		
SL <cr>See chapter SL commandSimilar to SW but including errorsGP<cr>P+0001.0<cr>Get preset tareGT<cr>T+0001.0<cr>Get grossGN<cr>G+0001.0<cr>Get netGW<cr>W+00010.0<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionMS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Send angle positions X and Y		
GP <cr>P+0001.0<cr>Get preset tareGT<cr>T+0001.0<cr>Get tareGG<cr>G+0001.0<cr>Get grossGN<cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>			(continuously)		
GT <cr>T+0001.0<cr>Get tareGG<cr>G+0001.0<cr>Get grossGN<cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionMG<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	SL <cr></cr>	See chapter SL command	Similar to SW but including errors		
GG <cr>G+0001.0<cr>Get grossGN<cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GP <cr></cr>	P+0001.0 <cr></cr>	Get preset tare		
GN <cr>N+0001.0<cr>Get netGW<cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionMG<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GT <cr></cr>	T+0001.0 <cr></cr>	Get tare		
GW <cr>W+00010+000103805<cr>Get net, gross, status and checksumGA<cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GG <cr></cr>	G+0001.0 <cr></cr>	Get gross		
GA <cr>A;+000.0;+000.0<cr>Get angle positions X and YGE<cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GN <cr></cr>	N+0001.0 <cr></cr>	Get net		
GE <cr>See chapter GE commandRead out of last 50 messagesGI<cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GW <cr></cr>	W+00010+000103805 <cr></cr>	Get net, gross, status and checksum		
GI <cr>See chapter GI commandRead out of general info and parametersGS<cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Get angle positions X and Y		
GS <cr>See chapter GS commandRead out of status and calibrationGL<cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GE <cr></cr>	See chapter GE command	Read out of last 50 messages		
GL <cr>See chapter GL commandRead out total log fileRE<cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GI <cr></cr>	See chapter GI command	Read out of general info and parameters		
RE <cr>See chapter RE commandReset the ERRORs database (passcode required)MN<cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GS <cr></cr>	See chapter GS command	Read out of status and calibration		
MN <cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	GL <cr></cr>	See chapter GL command	Read out total log file		
MN <cr>N+0001.0<cr>/ERR<cr>*4Get net, wait for no motionMG<cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>	RE <cr></cr>	See chapter RE command	Reset the ERRORs database (passcode		
MG <cr>G+0001.0<cr>/ERR<cr>*4Get gross, wait for no motionRS<cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr></cr></cr></cr>			required)		
RS <cr>S+0001.0;-01-<cr>Send and Reset Subtotal,AN<cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr></cr></cr>	MN <cr></cr>	N+0001.0 <cr>/ERR<cr>*4</cr></cr>	Get net, wait for no motion		
AN <cr>N+0001.0;0001<cr>/ERR<cr>*4Get net and alibi nr., wait for no motionAG<cr>G+0001.0;0001<cr>/ERR<cr>*4Get gross and alibi nr., wait for no motion</cr></cr></cr></cr></cr></cr>	MG <cr></cr>	G+0001.0 <cr>/ERR<cr>*4</cr></cr>	Get gross, wait for no motion		
AG <cr> G+0001.0;0001<cr>/ERR<cr>^{*4} Get gross and alibi nr., wait for no motion</cr></cr></cr>	RS <cr></cr>	S+0001.0;-01- <cr></cr>	Send and Reset Subtotal,		
motion	AN <cr></cr>	N+0001.0;0001 <cr>/ERR<cr>*4</cr></cr>	Get net and alibi nr., wait for no motion		
P85-123ABC-DEE456-CRN See chanter P85 command Set the Early module PLED's	AG <cr></cr>	G+0001.0;0001 <cr>/ERR<cr>*4</cr></cr>	-		
r objezono cjole i 450 konzel per chapiter r ob command e e per the norkinouule bleid s	P85;123ABC;DEF456 <cr></cr>	See chapter P85 command	Set the iForkmodule BLEiD's		

*1: If the scale is working in ranges with a number after the decimal point, the preset tare value should be given in accordingly. If the scale is working in ranges equal to or higher than 1 kg/lb, then the value should be entered with the decimal point at the end of the value. E.g. ranges 0.1/0.2/0.5 >> SP0001.5<CR>, ranges 1/2/5/10/20/50 >> SP00150.<CR>

*2: If an error state is active (like overload or underload) the SW-command should be renewed after the error state has been resolved.

*3: This is a special tare command which is mainly used with order picking applications. It cancels the previous tare and sets a new tare value which includes the old tare value and the added net weight. If the weight doesn't get stable within 5 seconds an error will be generated.

*4: In case the weight is not stable within 5 seconds, an error will be returned instead of the weight. Make sure the weight is stable and resend the command.

SERVICE commands

SERVICE command	Response string Operation					
GE <cr></cr>	See chapter GE command	Read out of last 50 messages				
GI <cr></cr>	See chapter GI command	Read out of general info and parameters				
GS <cr></cr>	See chapter GS command	Read out of status and calibration				
GL <cr></cr>	See chapter GL command	Read out total log file				
RE <cr></cr>	See chapter RE command	Reset the ERRORs database (passcode required)				
GA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Get angle positions X and Y				
SA <cr></cr>	A;+000.0;+000.0 <cr></cr>	Send angle positions X and Y (continuously)				

Special commands 'GW' and 'SW'

The 'GW' and 'SW' are commands with checksums. With these commands it is possible to get net, gross and status data. The respons string doesn't have the decimal point information. The 'SW' update rate is slower than the other commands.

W+000103805 <cr>Data IDNet valueGross valueStatus(hex)ChecksumEnd of string</cr>											
Data ID Net value Gross value Status(hex) Checksum End of string		W	+00010	+00010	38	05	<cr></cr>				
		Data ID	Net value	Gross value	Status(hex)	Checksum	End of string				

Structure of the response string:

Status bits:

Bit number	Bit definition	Status '0'	Status '1'
7 (MSB)	Indicator error	No errors	Indicator error
6	Tare active	No tare active	Tare active
5	Zero corrected	No zero correction	Zero corrected
4	Weight stable	Weight unstable	Weight stable
3	Within zero range	Out of zero range	Within zero range
2	Above max load	Under max load	Above max load
1	Setpoint 2 active	Setpoint 1 not	Setpoint 1 active
		active	
0 (LSB)	Setpoint 1 active	Setpoint 2 not	Setpoint 2 active
		active	

Example:

38 (hex) = 0011 1000(binair) bit 5, zero corrected bit 4, weight stable bit 3, within zero range

Calculating the checksum:

The checksum is the inverted sum of all ASCII characters in the response string previous to the checksum. Example:

Response string = W+00010+000103805<CR>

Add all hex values of the characters in the string. [W]+[+]+[0]+[0]+[0]+[1]+[0]+[+]+[0]+[0]+[0]+[1]+[0]+[3]+[8]Total is 2FA(hex) Remove the most significant digit, result is FA(hex) Invert the hexadecimal value, result is 05(hex) Convert the hexadecimal value to characters, result is [0][5]

Special commands 'AN' and 'AG'

With these special commands an extra value is send along together with the weight; the alibi number. It consists of 4 digits and is also saved in the indicators alibi memory. The number increases with every stored weighing.

The command works as follows:

• PC or terminal sends out the command AN or AG for demanding the net or gross weight respectively.

• Indicator waits for a maximum of 5 seconds for the weight to become stable, after which it returns the demanded weight accompanied by the alibi number under which this weighing was stored in the alibi memory of the indicator. The indicator display will show the weight and alibi no. stored 3x repeating after which it returns to the weighing mode. The subtotal is added in the background.

(NOTE: In case of no stable weight for more than 5 seconds an error will be send instead of the weight.)

• Format of the return string is: N+0001.0;0001<CR> or G+0001.0;0001<CR>

N = Net indicator

+ = sign indicator

0001.0 = weight value with decimal point

; = semi-colon separator sign

0001 = alibi number

<CR> = ending sign

Errors returned to PC

In case of an error in the display the PC will receive the following strings instead of a weight:

Error display *1	display *1 Error Response string Meaning				
	3200				
Err02	===== <cr></cr>	Above full scale			
Err06	===== <cr></cr>	Overload on AD converter			
	ERR <cr></cr>	Gross below zero range			
	ERR <cr></cr>	Underload on AD converter			
Err_L	===== <cr></cr>	out of level			
Side	ERR <cr></cr>	Side load error			
Тір	ERR <cr></cr>	Tip load error			

Error display*1	Error Response string	Meaning		
	5200 BLE			
Forks overloaded	N===== <cr></cr>	Gross above full scale		
Load cell overloaded	N===== <cr></cr>	Gross below zero range		
Not allowed	ERR <cr></cr>	Gross underload on AD converter		
Underload	N <cr></cr>	Gross overload on AD converter		
Not level	N <cr></cr>	Gross out of level		
Load not centered	N <cr></cr>	GW above full scale		
Load not centered	N <cr>*2</cr>	GW out of level		

Error display*1	Error Response string	Meaning		
	5200 HPT			
Overload (=====)	G===== <cr></cr>	Gross above full scale		
Underload (-)	G===== <cr></cr>	Gross below zero range		
Loadcell error (uuuuuu)	Guuuuuuu <cr></cr>	Gross underload on AD converter		
Loadcell error (00000)	G0000000 <cr></cr>	Gross overload on AD converter		
Not level ()	G <cr>*2</cr>	Gross out of level		
Overload (=====)	W=========A457 <cr></cr>	GW above full scale		
Not level ()	W	GW out of level		
Loadcell error (uuuuuu)	WuuuuuuuuuuB0BA <cr></cr>	GW underload on AD converter		
Loadcell error (oooooo)	WooooooooooB4DA <cr></cr>	GW overload on AD converter		

*1: All error messages can only be solved at the weighing system.

*2: Depending on the given command it will return a "G" for gross or a "N" for net.

Special command 'P85' (only for 3200 indicator used for servicing)

With this command you can set the BLEiD's of the forkmodules by PC connection. The BLEiD is printed on the label which is placed on the forkmodule. (only software version 1.01 and later)

Special command 'GE'

With this command the last 50 errors can be read out. In these 50 errors only the most important user errors, like tip-loading or side-loading handling errors are taken into consideration. In the table underneath these are marked with an asterisk "*". Other errors are summed up and will follow after the 50 errors have been sent. The transmission will be completed by sending out a form feed <FF>.

Example of Error logging:

Indicator 3200	Indicator 5200
01;71;170418;1400	01;02;110220;1206
02;71;300318;1232	02;01;070220;1414
03;71;300318;1232	02;01
04;71;300318;1448	03;03
05;02;130418;1409	04;01
06;02;130418;1417	21;10
07;02;130418;1419	22;12
08;02;130418;1419	23;20
09;02;130418;1419	24;22
10;02;130418;1419	40;21
11;71;130418;1613	92;04
12;71;130418;1634	01;02
13;02;130418;1728	41;17
14;71;130418;1730	<ff></ff>
15;71;170418;0836	
16;71;170418;0854	
17;71;170418;1359	
18;71;170418;1400	
01;0000	
02;0007	
03;0000	
04;0001	
06;0000	
08;0000	
09;0000	
10;0000	
21;0066	
22;0059	
23;0051	
24;0052	
25;0000	
26;0000	
40;0056	
41;0002	
42;0000	
43;0000	
44;0001	
45;0001	
46;0002	
60;0000	
61;0000	
<mark>62;0000</mark>	
<mark>71;0011</mark>	
72;0000	
80;0010	
81;0001	
92;0011	
98;0000	
99;0000	
<ff></ff>	

>

Explanation data lines

01;71;170418;1400 =

, ,		,														
0	1	;	7	1	;	1	7	0	4	1	8	;	1	4	0	0
regi	ster	Separation	error	no.	Sep.	D	D	Μ	М	Y	Υ	Sep.	Н	Н	М	М
coun	iter.	sign	displa	ayed	sign							sign				

The first error retrieved from the database was registered on the date 17th April 2018 at 14:00h and was error "71" which stands for unsafe tip-load handling.

71;0011 =

7	1	;	0	0	1	1		
error r	10.	Separation sign	Number of times displayed					

'71' which stands for tip-load handling, was registered 11 times since the unit has been put in the field.

Error list indicator 3200

function	Log No.	Displayed Text	
LOAD CELL SIGNAL UNSTABLE	1	"Err01" *	
IFORKS OVERLOADED ON MAXIMUM CAPACITY	2	"Err02" *	
TARA WHILE NEGATIVE WEIGHT	3	"Err03"	
ZERO OUT OF RANGE	4	"Err04"	
IFORKS OVERFLOW ADC	6	"Err06" *	
CALIBRATION OUT OF RANGE NEGATIVE	8	"Err08"	
CALIBRATION OUT OF RANGE SIGNAL TOO LOW	9	"Err09"	
CALIBRATION POINT LOWER THAN PREVIOUS POINT	10	"Err10"	
LOW BATTERY FORK 1 CRITICAL	11	"LoBAF"	
LOW BATTERY FORK 2 CRITICAL	12	"LoBAF"	
LOW BATTERY INDICATOR CRITICAL	13	"LoBAt"	
COMMUNICATION FAILURE FORK 1	21	"ErrF1"	
COMMUNICATION FAILURE FORK 2	22	"ErrF2" "Er_F1"	
COMMUNICATION FORK 1 TOO FEW SAMPLES received	23		
COMMUNICATION FORK 2 TOO FEW SAMPLES received	24	"Er_F2"	
COMMUNICATION FAILURE 1AD	25	"ErrAd"	
COMMUNICATION 1AD TOO FEW SAMPLES received	26	"Er_Ad"	
ERROR WITH CORRECTION SENSOR not found	39	"ErrCS"	
LEVEL MAX	40	"Err L"	
OIML restriction while printing	41	"OInnL"	
NTEP restriction while printing	42	"ntEP"	
OIML restriction while calibration	43	"OInnL"	
NTEP restriction while calibration	44	"ntEP"	
CALIBRATION NOT ALLOWED PROTECTED BY JUMPER	45	"Cal-J"	
AUDITTRAIL OUT OF RANGE *1	46	"SCall"	
LOW BAT INDICATOR	60		
LOW BAT FORK 1 (only active with wireless units)	61	F1 🖾	

LOW BAT FORK 2 (only active with wireless units)	62	F2 🖾
OFF CENTRE LOAD TIP (only active with wireless units)	71	"tiP" *
OFF CENTRE LOAD SIDE (only active with wireless units)	72	"SidE" *
ERROR in RDC transfer (only active whit RDC-a protocol)	80	"trErr"
RDC buffer full (only active whit RDC-a protocol)	81	"FULL"
ERROR EEPROM	82	"ErrEP"
GROSS NEGATIVE UNDERLOAD	92	""
CALIBRATION POINT MUST BE HIGHER THAN PREVIOUS ONE	98	"Err98"
ZEROING/TARING or PRINTING ACTION WHILE UNIT SWITCHED	99	"Err99"

*: These errors are registered in the P93 database with time and date stamp. All other errors will be shown as the number of times that they occurred and are only visible via the GE or GL command.

*1: This error will only occur when the system has been calibrated (CA_)or parameters (CF_) have been changed more than 99 times. It concerns only legal for trade scales. For non-legal for trade scales this message will never occur. In that case the audit trail numbers will return to 00.

In case of this error message a service visit from a RAVAS employee or RAVAS agent will always be needed to check the unit and if needed recalibrate and re-stamp the scale. A password [20399] is required for this.

function	Log No.	Displayed Text
ERROR NOT STABLE	1	"Weight not stable"
IFORKS OVERLOADED ON MAXIMUM CAPACITY	2	"Forks overloaded" *
TARA WHILE NEGATIVE WEIGHT	3	"Not allowed"
ZERO OUT OF RANGE	4	"Out of zero range"
IFORKS OVERFLOW ADC	6	"Load cell overloaded" *
CALIBRATION OUT OF RANGE NEGATIVE	8	"Negative weight"
CALIBRATION OUT OF RANGE SIGNAL TOO LOW	9	"LC signal too low"
CALIBRATION POINT LOWER THAN PREVIOUS POINT	10	"Cal. point too low"
LOW BATTERY FORK 1 CRITICAL	11	"Charge battery F1!"
LOW BATTERY FORK 2 CRITICAL	12	"Charge battery F2!"
LOW BATTERY INDICATOR CRITICAL	13	"Charge battery ind.!"
COMMUNICATION FAILURE FORK 1	21	"No signal F1"
COMMUNICATION FAILURE FORK 2	22	"No signal F2"
COMMUNICATION FORK 1 TOO FEW SAMPLES received	23	"Bad signal F1"
COMMUNICATION FORK 2 TOO FEW SAMPLES received	24	"Bad signal F2"
LEVEL MAX	40	"Not level"
OIML restriction while printing	41	"OIML not alllowed"
NTEP restriction while printing	42	"NTEP not allowed"
OIML restriction while calibration	43	"OIML Cal. locked"
NTEP restriction while calibration	44	"NTEP Cal. locked"
LOW BAT INDICATOR	60	"Low battery indicator"
LOW BAT FORK 1 (only active with wireless units)	61	"Low battery F1"
LOW BAT FORK 2 (only active with wireless units)	62	"Low battery F2"

Error list indicator 5200

		1
OFF CENTRE LOAD TIP (only active with wireless units)	71	"Load not centered" *
OFF CENTRE LOAD SIDE LEFT (only active with wireless units)	72	" Load not centered " *
OFF CENTRE LOAD SIDE RIGHT (only active with wireless units)	73	" Load not centered " *
ERROR in RDC transfer (only active whit RDC-a protocol)	80	"trErr"
RDC buffer full (only active whit RDC-a protocol)	81	"FULL"
ERROR EEPROM	82	"ErrEP"
GROSS NEGATIVE UNDERLOAD	92	"Underload"
ERROR FRAM	97	"FRAM error"
ZEROING/TARING or PRINTING ACTION WHILE UNIT SWITCHED	99	"Only in default units"
ERROR CONFIG	100	"Configuration error"
ERROR VERSION F1	101	"Wrong firmware F1"
ERROR VERSION F2	102	"Wrong firmware F2"
ERROR BARO TEMP	103	"Height sensor error"
OTHER BARO DISAGREE	104	"Height sensor error"
OTHER GSENSOR DISAGREE	105	"G-sensor error"
OTHER ACTION NOT PERMITTED IN CURRENT STATE	106	"Not allowed"
OTHER UNINSPECTED DATA RECEIVED	107	"Data mismatch"
OTHER TAC INVALID	108	"Invalid TAC code"
OTHER CAL INVALID	109	"Invalid CAL code"
OTHER ACTION NOT AVAILABLE	110	"Retry"
OTHER TARE ALREADY ACTIVE	111	"Tare already active"
OTHER PRESET TARE INVALID	112	"Preset tare invalid"
OTHER INVALID INPUT	113	"Invalid input"
OTHER CALIBRATION	114	"Calibration error"
OTHER IND POWER TOO LOW	115	"Ind. Power too low!!"

*: These errors are registered in the database with time and date stamp. All other errors will be shown as the number of times that they occurred and are only visible via the GE or GL command.

Special command 'RE'

With this command the list of errors can be reset to none. For this a password [5220<CR>] is required. All errors in the database of the indicator will be erased.

Only use this option if you want to start out with a fresh unit <u>after</u> a service.

Note that there is a difference in the way the response is handled between the indicator 3200 and indicator 5200. This is due to the fact that the 5200 has much more possible errors than the 3200 which would put a big pressure on the 5200's database if we would print them all each time. Therefore the 5200 only prints the recorded errors.

Example routine:

Command	Reply indicator			
	3200	5200		
RE <cr></cr>	PASSWORD?	PASSWORD?		
5220 <cr></cr>	ОК	OK		
GE <cr></cr>	01;0000	<ff></ff>		
	02;0000			
	03;0000			
	04;0000			

06;0000	
08;0000	
09;0000	
10;0000	
21;0000	
22;0000	
23;0000	
24;0000	
25;0000	
26;0000	
40;0000	
41;0000	
42;0000	
43;0000	
44;0000	
45;0000	
46;0000	
60;0000	
61;0000	
62;0000	
71;0000	
72;0000	
80;0000	
81;0000	
92;0000	
98;0000	
99;0000	
<ff></ff>	

Special command 'GI'

With this command the firmware versions of all the μ P's can be read out and all the settings of the parameters will be listed after which the transfer is ended by sending the form feed command <FF>.

Example of information logging indicator 3200:

STM;V0.21	(firmware release for the STM μ -processor on the main board)
NRFM;V0.3_t	(firmware release for the Nordic chip on the receiver option board)
NRFS;V0.6	(firmware release for the Nordic chip on the main board)
NRFT1;V0.7	(firmware release for the Nordic chip on the transmitter board F1)
NRFT2;V0.7	(firmware release for the Nordic chip on the transmitter board F2)
MacS;179DBD	(UID address for the Nordic chip on the main board)
<mark>Mac1;1E39CD</mark>	(UID address for the Nordic chip on the transmitter board F1)
<mark>Mac2;7</mark> C82C7	(UID address for the Nordic chip on the transmitter board F2)
P001;1	(setting of the start-up units)
P002;5	(setting of the smallest greaduation)
P003;10	(setting of the biggest graduation)
P004;1000	(setting of the maximum number of divisions)
P005;02500	(setting of the maximum capacity)
P006;0.5	(setting of the motion detection)
P007;3	(setting of the filter size)
P008;0.25	(setting of the zero track)
P009;002	(setting of the negative zero range)
P010;002	(setting of the positive zero range)
P012;n0	(setting of the power on zero mode)
P013;oinmL	(setting of the legal for trade version)
P015;n0	(setting of units switch activity)
P017;0	(setting of the Data Protocol for BLE in the SUP. menu)
P018;9.812	(setting of the gravity value working area)
P019;EU	(setting of the date/time format)
P020;9600	(setting of the baudrate for RS232 connection main board)
P021;8_n_1	(setting of the interface protocol for RS232 connection main board)
P023;05	(setting for the transmission rate of the remote protocol)
P024;Cr	(setting of the end character for RS232 connection main board)
P025;4	(setting of the Data Protocol for RS232 connection main board)
P026;4	(setting of the no. of LF for the RS232 connection main board)
P028;StAnd	(setting of the printout format)
P030;9600	(setting of the baudrate for COM3 connection main board)
P031;8_n_1	(setting of the interface protocol for COM3 connection main board)
P032;Cr	(setting of the end character for COM3 connection main board)
P035;6	(setting of the Data Protocol for COM3 connection main board)
P036;4	(setting of the no. of LF for the COM3 connection main board)
P040;G-SrA	(setting of leveling device mode)
P041;1	(setting of the delay time for the leveling device)
P042;1.00	(setting of the correction factor for +X direction leveling device)
P043;1.00	(setting of the correction factor for -X direction leveling device)
P044;1.00	(setting of the correction factor for +Y direction leveling device)
P045;1.00	(setting of the correction factor for -Y direction leveling device)
P046;3	(setting of the filter size for the leveling device)
P047;5.0	(setting of the switch off angle for the X direction lev. device)
P048;5.0	(setting of the switch off angle for the Y direction lev. device)
P049;002	(setting of the maximum allowed underload)
P060;FLt	(setting of the battery used for the indicator)
P061;02	(setting of the low battery switch off time for the indicator)
P062;3.7	(setting of the battery supply for the transmitter modules)
P063;120	(setting of the auto shut off time for the transmitter modules)
P064;08	(setting of the low batt. switch off time for the transm. Modules)
P068;00000	(setting not implemented yet > future use)
P070;YES	(setting of the clear tare mode) (setting of the maximum allowed tip-load)
P071;100	
P072;015	(setting of the maximum allowed side-load)
P080;0 P081;0.000	(setting of the corner calibration enabling)
FUO1;0.000	(setting of the corner correction factor for load cell A)

P082;0.000	<pre>(setting of the corner correction factor for load cell B)</pre>
P083;0.000	(setting of the corner correction factor for load cell C)
P084;0.000	(setting of the corner correction factor for load cell D)
P085;1E39Cd-7C82C7	(setting of the connected transmitter device UID's)
P086;6	(setting of the communication filter for the tranmitters)
P096;1	(setting of the hardware configuration)
P098;001	(setting of the terminal no.)
P122;00	(setting of the auto off function in USER menu)
P123;00	(setting of the sleep function in USER menu)
P124;01	(setting of the auto reconnect time transmission modules [fixed])
P125;20	(setting of back light off in USER menu)

Explanation data lines

STM;V0.21 =

S	Т	М	;	V	0	•	2	1
main p	rocesso	or STM	Separation sign	Firmware version			rsion	

The firmware version of the main processor of this device is V0.21. (4/9/2019: V1.01) NRFM;V0.3_t = Firmware version of the BLE-Master processor on the iFork receiver option board is V0.3_t. (4/9/2019: V0.8t, only visible for wireless units)

NRFS;V0.6 = Firmware version of the BLE-Slave processor on the main board is V0.6. (4/9/2019: V0.9)

NRFT1;V0.7 = Firmware version of the BLE processor of the iForks transmitter module 1 is V0.7. (4/9/2019: V2.0, only visible for wireless units) $*_1$

NRFT2;V0.7 = Firmware version of the BLE processor of the iForks transmitter module 2 is V0.7. (4/9/2019: V2.0, only visible for wireless units) $*_1$

MacS;179DBD

Μ	а	с	S	;	1	7	9	D	В	D
Mac address Bluetooth Slave		Separation	Mac address							
(fixed	(fixed on mainboard)			sign						

The Mac addressse of the Bluetooth modules are given.

MacS; ABC123 = Mac address of the Bluetooth Slave (placed directly on the main board) Mac1; ABC123 = Mac address of the Bluetooth Fork1 (placed on the iForks transmitter module 1, only visible for wireless units)

Mac2; ABC123 = Mac address of the Bluetooth Fork2 (placed on the iForks transmitter module 2, only visible for wireless units)

P001;1 =

	Р	0	0	1	;	1
Parameter no.				Separation sign	Setting of the parameter	

Parameter 001 was set on value 1 which stands for the start-up unit of the device. In this example that would be 'kg'. For the complete parameter list please see document [ms-ravas-

3200-eu-rev-20190919.pdf] for wired units or [ms-ravas-iforks-32-(xt)-eu-rev-20191128.pdf] for wireless units.

*1: The firmware versions of the transmitters should always be the same! If they differ the iForks are likely to malfunction. In that case uploading of firmware is necessary.

Example of information logging indicator 5200:

USER;Set Clock;Time;14:39:37 USER;Set Clock;Date;11-02-20 USER;Display_settings;Brightness;100% USER;Display_settings;Power_save;off USER; Display settings; Key functions; on USER; Display settings; Language; English USER; Display settings; Decimal point;, USER;Display_settings;Date_format;EU USER; Button Functions; Printer; Function; Print USER; Button Functions; Printer; Location; none USER; Button Functions; Send WiFi; Function; Send WiFi USER; Button_Functions; Send_WiFi; Location; none USER; Button Functions; Summing; Function; Add to total USER; Button_Functions; Summing; Location; Row1Button3 USER; Button Functions; Tare; Location; Row1Button4 USER; Button_Functions; PTARE; Location; Row1Button5 USER; Button Functions; Zero; Location; Row1Button6 USER; Button Functions; ID1SCAN; Location; none USER: Button Functions: ID2SCAN: Location: none USER; Button Functions; ID3SCAN; Location; none USER; Button Functions; ID4SCAN; Location; none USER; Button Functions; PT1SCAN; Location; none USER; Button Functions; PT2SCAN; Location; none USER;Button_Functions;TOGGLE_WEIGHT/PIECE;Location;none USER;Button_Functions;Reference_weight;Location;none USER; Button Functions; WEIGHING MODE; Location; none USER;Button Functions;PIECE COUNT MODE;Location;none USER; Button Functions; SCALE SELECTION; Location; none Service;Weigher;Settings;Unit_label;kg Service;Weigher;Settings;On screen type plate;on Service;Weigher;Settings;Scale Capacity:2500 Service;Weigher;Settings;Multi Range:2000 Service;Weigher;Settings;Step_Min:0 Service;Weigher;Settings;Step_Max:1 Service;Weigher;Settings;Gravity_Original:9812 Service; Weigher; Settings; Gravity Final: 9812 Service;Weigher;Settings;Legal_for_trade:1 Service;Weigher;Settings;Zero_track:0,2 Service;Weigher;Settings;Zero_range:50 Service;Weigher;Settings;Alibi:off Service;Weigher;Settings;Piece resolution:10 Service;Communication;Printer_settings;Linefeed:1 Service;Communication;Printer_settings;Header: Service;Communication;Printer_settings;Footer: Service;Communication;BLT4.0_on-board;Protocol:PC Service;Communication;RS232_on-board;Protocol:PC
Service;Communication;RS232_on-board;Stopbits:0 Service;Communication;RS232_on-board;Databits:15 Service; Communication; RS232 on-board; Parity:0 Service;Communication;RS232_on-board;Baudrate:9600 Service;Communication;USB on-board;SCAN ID:1170 Service;Communication;Com 10;Protocol:None Service;Communication;Com_10;Stopbits:0 Service;Communication;Com_10;Databits:15 Service; Communication; Com 10; Parity: None

Service;Communication;Com 10;Baudrate:9600 Service;Communication;Com_20;Protocol:None Service;Communication;Com 20;Stopbits:0 Service;Communication;Com 20;Databits:15 Service;Communication;Com_20;Parity:None Service;Communication;Com_20;Baudrate:9600 Service;Power_settings;Power_save_mode;Dim_timer:60
Service;Power_settings;Power_save_mode;Sleep_timer:300 Service; Power settings; Power save mode; Deep sleep timer:8 Service;Power_settings;Power_supply;Custom;100%_Voltage:120 Service;Power_settings;Power_supply;Custom;Low_bat_Voltage:108
Service;Power_settings;Power_supply;Custom;Absolute_shutdown:105 Service;Scale_type_software:BLE Service; Defaults; Button_Functions; Printer; Function; Print Service; Defaults; Printer; Location; none Service; Defaults; Button_Functions; Send_WiFi; Function; Send_WiFi Service; Defaults; Send WiFi; Location; none Service; Defaults; Summing; Send WiFi; Function; Add to total Service; Defaults; Summing; Location; Row1Button3 Service; Defaults; Tare; Location; Row1Button4 Service; Defaults; PTARE; Location; Row1Button5 Service;Defaults;Zero;Location;Row1Button6 Service; Defaults; ID1SCAN; Location; none Service; Defaults; ID2SCAN; Location; none Service; Defaults; ID3SCAN; Location; none Service; Defaults; ID4SCAN; Location; none Service; Defaults; PT1SCAN; Location; none Service; Defaults; PT2SCAN; Location; none Service;Defaults;TOGGLE WEIGHT/PIECE;Location;none Service; Defaults; Reference weight; Location; none Service;Defaults;WEIGHING MODE;Location;none Service;Defaults;PIECE_COUNT_MODE;Location;none
Service;Defaults;SCALE_SELECTION;Location;none Service;Defaults;Factory_reset;Print;Send_WiFi;Function;Print Service; Defaults; Factory reset; Print; Location; none Service; Defaults; Factory_reset; Send_WiFi; Send_WiFi; Function; Send_WiFi Service; Defaults; Factory_reset; Send_WiFi; Location; none Service; Defaults; Factory_reset; Summing; Send_WiFi; Function; Add_to_total Service; Defaults; Factory reset; Summing; Location; Row1Button3 Service;Defaults;Factory_reset;Tare;Location;Row1Button4 Service;Defaults;Factory_reset;PTARE;Location;Row1Button5
Service;Defaults;Factory_reset;Zero;Location;Row1Button6 Service; Defaults; Factory_reset; ID1SCAN; Location; none Service; Defaults; Factory_reset; ID2SCAN; Location; none Service;Defaults;Factory_reset;ID3SCAN;Location;none
Service;Defaults;Factory_reset;ID4SCAN;Location;none Service; Defaults; Factory_reset; PT1SCAN; Location; none Service;Defaults;Factory_reset;PT2SCAN;Location;none Service;Defaults;Factory_reset;TOGGLE_WEIGHT/PIECE;Location;none Service;Defaults;Factory_reset;Reference_weight;Location;none Service;Defaults;Factory_reset;WEIGHING_MODE;Location;none Service;Defaults;Factory_reset;PIECE_COUNT_MODE;Location;none Service;Defaults;Factory_reset;SCALE_SELECTION;Location;none NXP:1.0.7.1.0.A NRFM:1.0.t:1.0.t NRFS:1.0.1.9.0.0 NRFT1:0 NRFT2:0 MacS:RAVAS5200 D3F8C6 Mac1:3A4970 Mac2:4D4FB8 <FF>

Special command 'GS'

With this command the status of the device can be read out and information will be given about the calibration values and the last time a calibration and/or parameter setting had taken place. The data transfer will be ended with a form feed <FF>.

Example of status logging indicator 3200:

```
VF1;4.0
VF2;4.0
VFI;13.2
W+00185;G-000.17
LC1;-0001066
LC2;-0001076
LC3;+0676794
LC4;-0001477
GS0;-0021;+0051;+1017
GSA0;+090.27;-090.00
GS1;-0019
GS2;+0053
GS3;+1019
GSC;+0750;+0.00000;+0.00000;+0.00000;+0.00000;+0.00000;
CP0;-0001065;-0001074;-0001271;-0001470
CP1U; 01500; +1029207; +1029207; +1029207; +1029207; 00704.74
CP2U; 00000; +0000000; +0000000; +0000000; +0000000; 00000.00
CP3U; 00000; +0000000; +0000000; +0000000; +0000000; 00000.00
CP2D; 00000; +0000000; +0000000; +0000000; +0000000; 00000.00
CP3D; 00000; +0000000; +0000000; +0000000; +0000000; 00000.00
CorA;01.0000
CorB;01.0000
CorC;01.0000
CorD;01.0000
CF;77;120218;1315
CA;02;120218;1315
<FF>
```

Explanation data lines

VF1;4.0V =

Supply voltage of Fork1 is given in Volts. In this example it is 4.0 Volts. (only for wireless units)

VF2;4.0V =

Supply voltage of Fork2 is given in Volts. In this example it is 4.0 Volts. (only for wireless units)

VFI;13.2V =

Supply voltage of the indicator is given in Volts. In this example it is 13.2 Volts.

W±00185;G-000.17 =

The actual displayed weight in basic units (P01 depending) and present level of the G-sensor in fork 2 in grades(°) are given. In this example the actual weight is 185 kg and the number of grades in (driving direction) is 0.17°.

LC1;-0001066 = The actual number of AD counts of load cell input 1 is given. In this example -1066 counts. LC2;±123456 = The actual number of AD counts of load cell input 2 is given.

LC3;±123456 =

The actual number of AD counts of load cell input 3 is given. LC4;±123456 =

The actual number of AD counts of load cell input 4 is given.

In case of an 1AD unit (hand pallet truck scale with LC-junction board) these values would be expected to be the same but could actually differ in the last 3 numbers because of the delay of 100 msec. per reading. The first 4 numbers should be the same for a properly working unit.

In case of an iFork unit these values will be different because the outputs of the load cells will always differ a little.

If there is a big difference in one of the load cell outputs than this is an indication that the load cell might be defect or the capacity of that load cell differs from the capacity of the other load cells.

GS0;-0021;+0051;+1017 =

The calibrated X,Y and Z values of the G-sensor are given at zero degrees and zero load. In this example X value is -21 counts, the Y value is +51 counts and the Z value is +1017 counts. (only for wireless units)

GSA0;+090.27;-090.00 =

The calibrated values of raw X and raw Y at 0 calibration of the CS001 correction sensor. In this example X value is +90.27 and Y value is -90.00 (only for wired units)

GS1;-0019 =

The actual number of AD counts of G-sensor direction 1(X) is given. In this example -19 counts. (only for wireless units)

GS2;+0053 =

The actual number of AD counts of G-sensor direction 2(Y) is given. In this example +53 counts. (only for wireless units)

GS3;+1019 =

The actual number of AD counts of G-sensor direction 3(Z) is given. In this example +1019 counts. (only for wireless units)

GSC;750.0;0.00000;0.00000;0.00000;0.00000;00.0000;

The used calibration weight, the compensation factors for P1, P2, P3 and P4 and the level offset are given in this order {Cal_Weight};{P1_Comp}, {P2_Comp}; {P3_Comp}; {P4_Comp};{Loffset_kg}. In this example only a zero calibration was done for the G-sensor, leaving the values for the span calibration on 0. (only for wireless units)

CP0;-0001065;-0001074;-0001271;-0001470 =

The AD counts of the 4 LC's at 0 kg of the original weight calibration are given. In this example LC-A was -1065 counts, LC-B was -1074 counts, LC-C was -1271 counts and LC-D was -1470 counts.

CP1U; 01500;+1029207;+1029207;+1029207;+1029207;00704,74 =

The AD counts of the 4 LC's at the second calibration point UP of the original calibration are given as well as the gain factor. If as in this example no values are filled in the fields it means that no multi-calibration points were used.

CP3U; 00000;000000;000000;000000;000000;00000,00 =

The AD counts of the 4 LC's at the third calibration point UP of the original calibration are given as well as the gain factor.

CP1D; 00000;000000;000000;000000;000000;00000,00 =

The AD counts of the 4 LC's at the first calibration point DOWN of the original calibration are given as well as the gain factor. If as in this example no values are filled in the fields it means that the calibration down functionality was not used. This option is only available for approved weighing systems (P13 \neq nO)

CP2D; 00000;000000;000000;000000;000000;00000,00 =

The AD counts of the 4 LC's at the second calibration point DOWN of the original calibration are given as well as the gain factor.

CP1D; 00500;000000;000000;000000;000000;00000,00 =

The AD counts of the 4 LC's at the third calibration point DOWN of the original calibration are given as well as the gain factor.

CorA;1.000 =

The correction factor at the original calibration for corner A is given. In this example no correction factors are given which means no corner calibration has been performed which makes sense for a wired 1AD unit.

For wireless units these factors would normally be different for each corner since each load cell has its own characteristics which slightly differ from each other and the mechanical construction influences this during the replacement of the weight.

CorB; 1.000 =

The correction factor at the original calibration for corner B is given.

CorC; 1.000 =

The correction factor at the original calibration for corner C is given.

CorD; 1.000 =

The correction factor at the original calibration for corner D is given.

CF;00;061017;1533 =

Present audit trail number {00] for the parameter setting with the time stamp [6th October 2017 at 15:33h]

CA;00;061017;1533 =

Present audit trail number for the calibration [00] with the time stamp [6th October 2017 at 15:33h]

Example of status logging indicator 5200:


VF1:3.8<CR> VF2:3.9<CR> VFI:14.9<CR> W+01165.G+0.3833G-0.1599<CR> LcA:175239<CR> LcB:4223443<CR> LcC:3666762<CR> LcD:712731<CR> F1 GS0;22;0;1031<CR> F2_GS0;15;-4;1016<CR> GSA0;0;0<CR> F1_GS1;29<CR> F1 GS2;-3<CR> F1 GS3;1049<CR> F2_GS1;0<CR> F2_GS2;-13<CR> F2 GS3;1041<CR> GSC;+00000.;-0.0012;-0.0013;+0.0000;+0.0000;+0.0040<CR> CP0;0;293337;240334;193728;289420;+0.0000<CR> CP1U; 1500; 2528895; 2490806; 2494138; 3129453; +0.0000<CR> CP2U; 2500; 2043407; 1711195; 4317352; 3915846; -0.0231<CR> CP3U;0;0;0;0;0;+0.0000<CR> CP4U;0;0;0;0;0;0;+0.0000<CR> CP1D;0;0;0;0;0;+0.0000<CR> CP2D;0;0;0;0;0;0;+0.0000<CR> CP3D;0;0;0;0;0;+0.0000<CR> CP4D;0;0;0;0;0;0;+0.0000<CR> CorA;+01.609<CR> CorB;+01.109<CR> CorC;+00.804<CR> CorD;+00.477<CR> TAC;13;110220;1358<CR> CAL;14;110220;1343<CR> <FF>

Note that some of the data is slightly different from the data response by indicator 3200 but those are minor differences due to different firmware setup.

Special command 'GL'

This command is used to retrieve all data of the commands 'GE', 'GI' and 'GS' combined in one dataflow without the form feeds in between but only a form feed at the end.


So the response would be the response at 'GE' minus the form feed, followed by the response at 'GI' minus the form feed, followed by the response at 'GS' with the form feed.



In the RAVAS APP this command is automatically generated when pressing the [Upload Log File] button in the menu {About Us}.

You will be asked to send the saved log. The default email address is service @ravas.com. You may replace it by another address or add it with another email address.

In the email you will see the data as a CSV file as well as directly on the screen:



Special command [SL] (Version 0.32 and higher)

This command is used for customers who needs to have the proper error message in his reply to be able to perform the right action in his terminal.

The command is resembling the [SW]-command but in case of an error in the indicators display it will return the error number. For example; <ERR40> in case of a tilted position. The error numbers resemble the numbers of the errors list mentioned in the [GE]-command. It will be transmitted 2x/second. As soon as the error situation has been solved it will display the weight-string again.

In case of low battery of the forks it will also be transmitted but only once every 30 seconds. Only if the batteries are completely empty and the display of the indicator mentions "LOBAF", it will be transmitted 2x/second as well since this is a critical situation.