

US-4011 DIGITAL INDICATOR



OUR SCALE GUARANTEE

- Easy to setup
- Easy to use
- Easy replacement parts
- Easy calibration/phone support
- Long warranty support
- 30 day money back guarantee
- Lowest price guarantee

CALL NOW: 800-711-2237



US-4011 DIGITAL INDICATOR

USA Measurements US-4011 LCD indicator features a large easy to read digital display. Our easy to use indicator can be used in a variety of weighing applications. Such as livestock, recycling, ltl freight, fishing applications, and distilleries. The indicator is commonly used with our bench scales, floor scales, shipping scales, livestock scales, and pallet jack scales.

US-4011

MODEL NUMBER

US-4011

The US-4011 indicator powers up to (4) 350 ohm load cells, has a built in bright LCD display, and operates on AA batteries. The indicator features functions for: check weighing, counting parts, and tare function. Our US-4011 is user friendly and can be calibrated by any owner.

US-4011 INDICATOR FEATURES:

- LCD Backlight Display
- Net, Total, Hold, Zero, & Peak
- Units: Lb, Oz, Kg, Lb:oz, grams, % weight
- Counting Function
- Battery Powered
- 110V Power Adapter
- 4xAA Batteries (Included)
- Check weigh Function (Hi/Ok/Lo)
- USB and RS-232 Output
- Powers (4) 350 ohm Load Cells
- Dimensions: 9.5"x4.9"x2.5"
- Operating Temp: -10°C to 40°C (14°F to 104°F)