US-5011 DIGITAL INDICATOR















FRED'S PERSONAL **GUARANTEE**

- · Easy to setup
- Easy to use
- Easy replacement parts
- Easy calibration/phone support
- Long warranty support
- 30 day money back guarantee
- Lowest price guarantee

CALL NOW: 858-484-8000







US-5011 DIGITAL INDICATOR LCD DISPLAY

USA Measurements US-5011 LCD indicator features a large easy to read digital display. Our easy to use indicator can be used in a variety of weighing applications. Such as livestock, recycling, ltl freight, fishing applications, and distilleries. The indicator is commonly used with our bench scales, floor scales, shipping scales, livestock scales, and pallet jack scales.

US-5011

MODEL NUMBER

US-5011

The US-5011 indicator powers up to (4) 350 ohm load cells, has a built in bright LCD display, and operates on AA batteries. Our US-5011 is very user friendly and can be calibrated by any owner.

US-5011 INDICATOR FEATURES:

- LCD Backlight Display
- Zero, Net, Hold, & Tare
- · Units: Ib or kg
- Simple Design
- · Battery Powered
- 110V Power Adapter

- 4xAA Batteries (Included)
- USB and RS-232 Output
- Powers (4) 350 ohm Load Cells
- Dimensions: 9.5"x4.9"x2.5"
- Operating Temp: -10°C to 40°C (14°F to 104°F)