US-7011 DIGITAL INDICATOR LCD DISPLAY













- · Easy to setup
- · Easy to use
- Easy replacement parts
- · Easy calibration/phone support
- Easy warranty support
- 30 day money back guarantee
- Lowest price guarantee

CALL NOW: 800-711-2237



US-7011 INDICATOR FEATURES

- Steel Enclosure Around Indicator
- Steady performance PCB board
- Multiple weighing units: (lb/oz/kg)
- · Gross/Tare/Zero
- · Low power design, longer battery usage time
- · Hold function, locks the weight
- Idle mode and automatic power off function
- · Low-battery detection and warning
- 6 digits 0.7" tall LCD display with backlight
- Splash proof keyboard and display
- RS232 Output
- · Print to an optima scale ticket printer
- · Stainless steel wall mount bracket included

INTERCHANGEABLE PRODUCTS

- MS-7515
- OP-902
- SL-7515
- SL-902
- LP-7515

US-7011 DIGITAL INDICATOR LCD DISPLAY

The US-7011 indicator powers up to (4) 350 ohm load cells, has a built in LCD display, and operates on AA batteries or AC adapter. The easy to use indicator comes featured with the following functions: gross, tare, zero, and hold function. Our US-7011 is user friendly and can be calibrated by any user.

PACKAGE INCLUDES

- (1) US-7011 Digital LCD Indicator
- · (3) AA Batteries
- (1) AC Power Adapter
- (1) 15' Home Run Cable
- (1) Owner's Manual
- · Stainless Steel Mounting Bracket

OPTIONAL ACCESSORIES

- Thermal Printer
- Indicator Stand (stainless steel)
- · Certificate of Calibration